

AVN4430 Phone compatibility List

Software Version App 7.825 (8816/090827) OS: 327431  
Bluetooth Device

Brand Name	Model Name	Carrier	Software Ver.	Pairing		APN (TomTom service)	Phone book transfer	SMS (Text)		Calling						Reconnection					Note		
				Phone is discovered	Phone is paired			Send	Receive	Out going	In coming	End call	Hold	Call ID	DTMF	Discrete mode	ACC-ON	Restart phone	Restart phone's BT	Restart PND		Restart PND' BT	Reset PND
Apple	iPhone 3GS 16GB	ATT	3.1.3 (7E18)	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Blackberry	Pearl 8110	ATT	v4.5.0.182 (Platform 2.7.0.106)	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
Blackberry	Bold 9700	T-Mobile	v5.0.0.330	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	
Blackberry	Curve 8520	T-Mobile	v4.6.1.259 (Platform 4.2.0.116)	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Blackberry	Storm2 9550	Verizon	V5.0.0.320	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
Garmin	Nuvifone	ATT	v: 4.35.3	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Google	Nexus One phone	T-Mobile	Android Version 2.2	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
HTC	Tilt2 T7377	ATT	Windows Mobile 6.5 Pro. CE OS 5.2.21849	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	NG	OK	OK	OK	
HTC	HTC Snap	Sprint	Windows Mobile 6.1 Standard CD OS 5.2.21041	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK( 1)	OK	OK	OK	OK	OK	OK	1 The unit will go to discrete mode but will not return to BT-HF mode. You may have to reconnect the BT manually through the phone.
HTC	HTC Hero	Sprint	Firmware 1.5 software 1.56.651.2	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
HTC	Touch Pro 2	T-Mobile	Windows Mobile 6.5 Pro. CE OS 5.2.21881	OK	OK	OK	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
HTC	HD2	T-Mobile	Windows Mobile 6.5 Pro. CE OS 5.2.21881	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
HTC	Droid Eris	Verizon	Firmware 2.1 Software 2.37.605.4	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK( 1)	OK	OK	OK	OK	OK	OK	NG	OK	OK	1 After hanging up on the second call, the unit rings again with the first call and you need to answer instead of switching the first call immediately.
HTC	Touch Pro 2	Verizon		OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	NG	NG	NG	NG	NG	
HTC	Imagio	Verizon	Windows Mobile 6.5 CE OS 5.2.21849	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	NG	NG	OK	OK	OK	
HTC	Ozone XV6175	Verizon	Windows Mobile 6.1 Standard CE OS 5.2.21041	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	NG	
LG	Shine II Silver	ATT	GD710-V10f-SEP-25-2009-ATT-US	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
LG	Lotus Elite LX610	Sprint	LX610V04	OK	OK	NG	OK	NG	OK	OK	OK	OK	NG	OK	NG	OK( 1)	OK	OK	OK	OK	OK	OK	1 The unit will go to discrete mode but will not return to BT-HF mode. You may have to reconnect the BT manually through the phone.
LG	Rumor2 LX265	Sprint	LX265V05	OK	OK	NG	OK	NG	NG	OK	NG	OK	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	
LG	LX290	Sprint	LX290S04 Rev 1.1	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
LG	LX370	Sprint	LX370V05 Rev 1.1	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK( 1)	OK	OK	OK	OK	OK	OK	1 The unit will go to discrete mode but will not return to BT-HF mode. You may have to reconnect the BT manually through the phone.
LG	Accolade VX5600	Verizon	N/A	OK	OK	NG	NG	NG	OK	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
LG	Chocolate Touch VX8575	Verizon	VX857V05 Bluetooth 2.1+EDR Hardware Revision 1.0	OK	OK	NG	NG	NG	OK	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
Motorola	Backflip MB300	ATT	Blur_Version.012.1199.MB300.ATT.en.us Firmware Version 1.5	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Motorola	Tundra VA76R	ATT	AP S/W V: R63715_U_71.01.7CR	OK	OK( 1)	NG	OK	NG	NG	NG	NG	OK	OK	OK	NG	OK	NG	NG	NG	NG	NG	NG	1 Pairing sometimes fails.
Motorola	Brute i681	Sprint	N/A	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	NG	NG	OK	OK	
Motorola	Debut i856	Sprint	N/A	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	NG	OK	OK	OK	
Motorola	Clutch i465	Sprint	N/A	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	OK	OK	OK	OK	
Motorola	Cliq	T-Mobile	Blur_Version.1.3.18.MB20 Firmware Version 1.50.T-Mobile.en.US	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Motorola	Barrage	Verizon	Blur_Version.1.3.18.MB200.T-Mobile.en.US Firmware Version 1.5	OK	OK	NG	OK	NG	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Motorola	Droid	Verizon	Firmware 2.0.1	OK	OK	NG	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK( 1)	OK	OK	OK	NG	OK	OK	1 The unit will go to discrete mode but will not return to BT-HF mode. You may have to reconnect the BT manually through the phone.
Nokia	Mural 6750	ATT	V 4.96 22-09-09 RM-381	OK	OK	NG	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Nokia	6350	ATT	V 12.40 22-03-10 RM-455	OK	OK	NG	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Nokia	5130	T-Mobile	N/A	OK	OK	OK	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Nokia	3711	T-Mobile	3.8	OK	OK	OK	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Nokia	8301	T-Mobile	V05.93 16-04-08 RM-323 © Nokia	OK	OK	OK	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Nokia	2760	T-Mobile	N/A	OK	OK	NG	OK	OK	NG	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Nokia	N86	unlock (ATT or T-Mobile)	21.006	OK	OK	OK	NG	NG	NG	OK	OK	OK	NG	OK	NG	NG	OK	OK	NG	OK	OK	OK	
Nokia	N85	unlock (ATT or T-Mobile)	11.047	OK	OK	NG	NG	NG	NG	NG	OK	OK	NG	OK	NG	NG	NG	NG	NG	NG	NG	NG	
Nokia	E66	unlock (ATT or T-Mobile)	N/A	OK	OK	OK	OK	NG	NG	OK	OK	OK	NG	OK	NG	OK	OK	OK	NG	OK	OK	OK	

